

Page 1

: Wednesday, May 18, 2011 12:32:37 PM Item ID: D3324-041 Accept Revision ID: Basket Base Assembly 'Item Name: **Start Date:** 5/18/2011 Start Qty: 1.00 **Cust Item ID:** Required Date: 5/23/2011 Req'd Qty: 1.00 **Customer:** Reference: Date: <u>//-05-/8</u> Tooling: Approvals: Process Plan: Date: Date: SPC (Y/N): Date: Sequence ID/ Operation Set Up/ **Tool ID** Tool # Plan **Work Center ID** Description **Run Hours Draw Nbr Revision Nbr** D3324 Rev B 100 0.00 Large Fab Large Fab 0.00 Memo Large Fab 1-Cut tubes as per Dwg D3324 Description Part Number Bottom Tube D3324-1 D3324-3 Full Length Tube D3324-5 Top End Tube D3324-7 Bottom EndTube D3324-9 Vertical Tube M112786 M/00075

Setup Start

Stop

Start

Stop

Reject

Number

Insp.

Stamp

Reject

Oty

Run

Accept

Qty

Code



Quality Control -

'Memo

QC9- Inspect visual per QSI004- Fusion Welds

0.00

0.00

W/O:			1	V	VORK ORDER CHANGI	ES		*				
DATE	STEP	PRO	OCEDU	RE CH	HANGE		Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector	
		÷										
Part No		PAR #:		ł								
	R	esolution:	Dis	posit	tion:	_ QA:	QA: N/C Closed: Date:					
NCR:			WORK	OR	DER NON-CONFORMA	NCE	(NCR)					
DATE	STEP	Description of NC Section A		itial f Eng	Corrective Action Section Action Description Chief Eng	on B	Sign & Date	Verifica Section		Approval Chief Eng	Approval QC inspector	
			Crite	ar Eng	Chief Eng		Date					
	:					:						
		•										
								·	-			
				ļ								
									•	1		
									1			
								~		,*		

Wednesday, May 18, 2011 12:32:37 PM



Page 2

Item ID:

D3324-041

Accept

Setup Start



Revision ID:

Item Name:

Basket Base Assembly

Start Date:

5/18/2011

Start Qty: 1.00

Required Date: 5/23/2011

Req'd Qty: 1.00



Cust Item ID: Customer:

Tool ID

Reference:

Approvals:

Process Plan:

Date:

Date:

Tooling:

SPC (Y/N):

Date: Date: Start

Stop

Stop

Sequence ID/

Work Center ID

120

Quality Control

Operation Description

QC5-Inspect part completeness to step on W/O

Memo

Set Up/

Run Hours

11/05/26

Tool # Plan

Accept Code Qty

Reject Qty

Run

Reject Number

Insp. Stamp

121

HandFinish

Hand Finishing

Pressure Wash per QSI005 4.3

0.00

Memo

0.00

BL 11-5-26

Dart A	Aeros	pace	Ltd
--------	-------	------	-----

W/O:				WORK ORDER CHANGE	S				
DATE	STEP	PROCE	DURE (CHANGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
									; :
Part No	•	PAR #:	Fault (Category:	NCR: Yes	No DQ	\ :	Date:	
	R	esolution:	l l					Date: _	
NCR:		WO	RK O	ORDER NON-CONFORMA	NCE (NCF	()			
DATE	STEP	Description of NC Section A	Initial	Corrective Action Section Action Description	Sign 8	Verific Section		Approval Chief Eng	Approval QC Inspector
			Chief En	ng Chief Eng	Date				
	į								
				·					
-									

Wednesday, May 18, 2011 12:32:37 PM



Page 3

D3324-041 Item ID: **Revision ID:** Basket Base Assembly Item Name:

Start Date: 5/18/2011

Start Qty: 1.00 Req'd Qty: 1.00

Required Date: 5/23/2011

Accept



Run

Accept

Qty

Setup Start



Cust Item ID:

Customer:

Tool ID

Reference:

А	DD	rov	va l	s:

Process Plan:

Date: Date:

Tooling:

SPC (Y/N):

Set Up/

Run Hours

Date:

Date:

Tool # Plan

Code

Reject

Oty

Start Stop

Stop



Number Stamp

Bl 11-5-27.

Insp.

Sequence ID/ Work Center ID

130



Powdercoat

Powder Coating

Operation Description

White Gloss(Ref:4.3.5.1) per QSI005 4.3-Alum

Memo

0.00

0.00

START TIME: OVEN TEMPERATURE FINISH TIME:

****** 2nd coat if necessary 2ND COAT:

START TIME:

OVEN TEMPERATURE:

140

QC3- Inspect Part Finish

0.00

Quality Control

Memo

0.00

Reject

W/O:			V	VORK ORDER CHANGES						
DATE	STEP	PROCEDU	RE CH	HANGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector	
D- 4 N-										
Part No		PAR #: Fa	l l							
	R	esolution: Di						Date: _		
NCR:		WORI	∮OR	DER NON-CONFORMANC	E (NCF	R)				
DATE	STEP		nitial ief Eng	Corrective Action Section B Action Description Chief Eng	Sign &	Sect.	cation ion C	Approval Chief Eng	Approval QC Inspector	
			19	Shiot Eng						

Wednesday, May 18, 2011 12:32:37 PM



Page 4

Item ID:

D3324-041

Accept

Setup Start

Stop

Start

Stop



Revision ID:

Item Name:

Basket Base Assembly

Start Date:

Required Date: 5/23/2011

5/18/2011

Start Qty: 1.00

Req'd Qty: 1.00



Cust Item ID:

Customer:

Reference:

Approvals:

QC:

Process Plan:

Date:

Date:

SPC (Y/N):

Tooling:

Date:

Date:

Code

Qty

Reject Accept Qty

Run

Reject Number Stamp

Insp.

Sequence ID/ **Work Center ID**

150

Packaging

Packaging

Operation Description

Identify as per dwg & Stock Location:

Set Up/ **Run Hours**

0.00

0.00

SB 1165/07

Tool ID

Tool # Plan

160

QC

Quality Control

QC21- Final Inspection - Work Order Release

Memo

0.00

0.00

W/O:				WC	RK ORDER CHANGE	ES					
DATE	STEP	PRO	CEDURE	E CHAI	NGE	В	/	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
Part No	:	PAR #:	Faul	t Cate	gory:	NCR: \	es N	o DQ	A:	Date:	
	R	esolution:	Disp	position: Date: Date:							
NCR:			WORK	ORD	R NON-CONFORMA	NCE (N	ICR)				
De		Description of NC		Corrective Action Section B			Verification		cation	Approval A	Approval
DATE	STEP	Section A	Initi Chief E		Action Description Chief Eng		gn & Date	Section C		Chief Eng	QC Inspector
								E .			
•								1			
i											

NOTE: Date & initial all entries

Picklist Print

Wednesday, May 18, 2011 12:32:47 PM

Work Order ID: 69752

Parent Item:

D3324-041

Basket Base Assembly Parent Item Name:



Start Date: 5/18/2011

Start Qty: 1.00

Required Date: 5/23/2011

Page 1

Required Qty: 1.00

Comments:

IPP Rev:A□05.02.09□New issue□KJ/JLM□

IPP Rev:B 08-12-16 attach DEO DD verified by:EC

Component Item ID/ Item Name	Replacement Item ID	Mfg/ Purch	Bin Item	Primary Location	Last Location	Route Seq ID	Unit of Measure	Qty on Hand	Qty per Kit	Total Qty	Qty Issued	Date Issued	Status
D3328-3 Basket Hinge		Manufactured	No			100	Each	32.0000	2	2	(let	5.2	26
				Location WA005	33872	<u>Loc (</u>	2ty 32 32	Loc Code	_	2	-		
D3348-1 Clevis		Manufactured	No			100	Each	21.0000	4 	4	1000	<u>5.20</u>	26
				Location		Loc (Loc Code					
D3349-3 Spacer Bushing		Manufactured	No	WA005	44246	100	21 21 Each	8.0000	2	2 H 10	05.2	5	
			•	Location		Loc (Loc Code					
D3367-1 Mounting Bracket		Manufactured	No	WA005	41831	100	8 8 Each	36.0000	2	2 2 M	- - !!, E	5.2	<u>.</u>
J				Location WA005	43228	<u>Loc (</u>	36 36	Loc Code	_	2	_		

W/O:				W	ORK ORDER CHANG	ES					
DATE	STEP	PRO	CEDUR	E CH	ANGE		Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC inspector
		*				-		•			
Part No	:	PAR #:	Fau	It Cat	egory:	_ NC	R: Yes I	No DQA	\:	Date:	
Resolution: D											
NCR:			WORK	ORI	DER NON-CONFORMA	NCE	(NCR)			
DATE	STEP	Description of NC Section A	Init	ial	Corrective Action Section Action Description	on B	Sign &	Verific Section		Approval Chief Eng	Approval QC Inspector
****		Section A	Chief		Chief Eng		Date	Secil)II C	Office Eng	QC IIIspector
		`									
•											
								:			
											1

NOTE: Date & initial all entries

Wednesday, May 18, 2011 12:32:48 PM

Work Order ID: 69752

Parent Item:

D3324-041

Parent Item Name: Basket Base Assembly



Start Date: 5/18/2011

Required Date: 5/23/2011

Start Qty: 1.00

Required Oty: 1.00

M4130NTS0.500W.035

569 Expanded Metal

4130 Square tube .500 x .500 x .035w

Purchased No 100

555.7500


Loc Code

46.6

49.05263

M569EX0.50-18F Purchased No

Location	<u>L</u>	oc Oty
MAT034		555.75
109127		216
109385		15.75
$(11\overline{2}786)$		324
	100	sf







11.05.26

Location	
MAT018	
	12776

Loc Code

Dart	Aeros	pace	Ltd
------	--------------	------	-----


				1							
W/O:				V	ORK ORDER CHANGES						
DATE	STEP	PROC	EDUF	RE CH	ANGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector	
						·	•				
····		·									
Part No	•	PAR #:	_ Fau	It Ca	egory:	NCR: Yes	No DQ	A:	Date: _		
Resolution:			Disposition: Q			QA: N/C Closed: Date:					
NCR:		W	ORK	OR	DER NON-CONFORMAN	CE (NC	₹)				
DATE	STEP	Description of NC			Corrective Action Section B			cation	Approval	Approval	
	SILF	Section A		tial Eng	Action Description Chief Eng	Sign of Date		Section C	Chief Eng	QC Inspector	
								. • • • •			
										-	
										- 1	
					Tala.						



	DESIGN DRAWN BY			DART AEROSPACE LTD HAWKESBURY, ONTARIO, CANADA					
- 1	CHEC	(ED ₄ /	APPROVED /	DRAWING NO.	REV. B				
1		#	#	D3324 SHEET	1 OF 3				
	DATE	<u> </u>	<u></u>	TITLE	SCALE				
	05.0	3.04		BASKET BASE ASSEMBLY	NTS				
	Α		04.10.20	NEW ISSUE					
	В		05.03.04	UPDATE MESH MATERIAL SPEC					

PARTS LIST FOR D3324-041 BASKET BASE ASSEMBLY

Part No.	Quantity (-041)	Length A	Length B	Length C	Description
D3324-1	3	14.00	N/A	N/A	BOTTOM TUBE
D3324-3	4	N/A	86.50	N/A	FULL LENGTH TUBE
D3324-5	2	N/A	16.00	N/A	TOP END TUBE
D3324-7	2	N/A	15.00	N/A	BOTTOM END TUBE
D3324-9	10	N/A	N/A	11.04	VERTICAL TUBE
D3328-3	2	N/A	N/A	N/A	HINGE PLATE
D3348-1	4	N/A	N/A	N/A	CLEVIS
D3349-3	2	N/A	N/A	N/A	SPACER BUSHING
D3367-1	2	N/A	N/A	N/A	MOUNTING BRACKET




D3324-1/-3/-5/-7/-9

- 1) CUT LENGTH/SHAPE PER DIAGRAM AND PARTS LIST
- 2) MATERIAL: 4130 COND. N SQ. TUBE PER MIL-T-6736, 1/2" SQ. x 0.035 WALL (REF. DART SPEC M4130N-TS0.500W.035)
- 3) ALL DIMENSIONS ARE IN INCHES
- 4) TOLERANCES ARE PER DART QSI 018 UNLESS OTHERWISE NOTED

Copyright @ 2005 by DART AEROSPACE LTD

THIS DOCUMENT IS PRIVATE AND CONFIDENTIAL AND IS SUPPLIED ON THE EXPRESS CONDITION THAT IT IS NOT TO BE USED FOR ANY PURPOSE OR COPIED OR COMMUNICATED TO ANY OTHER PERSON WITHOUT WRITTEN PERMISSION FROM DART AEROSPACE LTD.

W/O:		WORK ORDER CHANGES										
DATE	STEP	P		Ву	Date Q	ty Approval Chief Eng / Prod Mgr	Approval QC Inspector					
									,			
							·					
÷ .									-			
Part No		PAR #:	Fault Ca	tegory:	N	CR: Yes	No DQA: _	Date: _				
	R	esolution:	Disposit	ion:	c	A: N/C CI	osed:	ed: Date:				
NCR:	<i>".</i> .		WORK OR	DER NON-CO	VFORMANO	CE (NCR	3)					
DATE	STEP	Description of NC	1.34.1	Corrective Acti		Sign &	Verification		Approval			
	0.2.	Section A	Initial Chief Eng	Action De Chief		Date	Section C	Chief Eng	QC Inspector			




W/O:			W	ANGES								
DATE	STEP	PRO	CEDURE CH	ANGE		Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector		
										·		
		·										
Part No:		PAR #:	Fault Ca	tegory:	NCR: Yes No DQA: Date:							
	R	esolution:	Disposit	ion:	QA: N/C Closed: Date:							
NCR:		V	VORK OR	DER NON-CONFO	PRMANCE	(NCR)						
DATE	0750	Description of NC		Section B	veritic			tion Approval	Approval			
DATE	STEP	Section A	Initial Chief Eng	Action Descri Chief Eng	otion	Sign & Date	Section C		Chief Eng	QC Inspector		
										<u> </u>		
		}										
i												
	1	I .	1	1		1	1		,	1		

H:\fFORMS\Quality Assurance\approved QA\NCRWO RevE



DESIGN	PH	DART AEROSPACI HAWKESBURY, ONTARIO, CA	
CHECKED	APPROVED	DRAWING NO.	REV. B
#	AH .	D3324	SHEET 3 OF 3
DATE		TITLE	SCALE
05.03.04		BASKET BASE ASSEMBLY	1:8




Copyright © 2005 by DART AEROSPACE LTD

THIS DOCUMENT IS PRIVATE AND CONFIDENTIAL AND IS SUPPLIED ON THE EXPRESS CONDITION THAT IT IS NOT TO BE USED FOR ANY PURPOSE OR COPIED OR COMMUNICATED TO ANY OTHER PERSON WITHOUT WRITTEN PERMISSION FROM DART AEROSPACE LTD.

Dart Aerospace	Ltd
----------------	------------

W/O:			WC	ANGES								
DATE	STEP	PR		Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector				
: :					İ							
							1.00					
				· · · · · · · · · · · · · · · · · · ·								
Part No:		PAR #:	Fault Cate	gory:	NCR: Yes No DQA: Date:							
	R				QA: N/C Closed: Date:							
NCR:			WORK ORD	ER NON-CONF	PRMANCI	E (NCF	1)					
DATE	STEP	Description of NC		Section B	VARITICS			on Approval	Approval			
DAIL		Section A	Initial Chief Eng	Action Descri	ption 	Sign 8 Date	Secti	on C	Chief Eng	QC Inspector		
						İ			1			

H:\fFORMS\Quality Assurance\approved QA\NCRWO RevE



									
W/O:				WORK	ORDER CHANG	ES			
DATE	STEP		PROCEDURE	CHANGE		Ву	Date Q	Approval Chief Eng / Prod Mgr	Approval QC Inspector
•.			·					, :	
Part No		PAR #: _							
Resolution:								Date: _	
NCR:	. •		WORK	DRDER	NON-CONFORMA	NCE (NCR)		
DATE	OTED	Description of NC			rective Action Section		Verification	n Approval	Approval
DATE	STEP	Section A	Initi Chief (Action Description Chief Eng	Sign & Date	Section C		QC Inspector
No. No.					·				-
								,	

NOTE: Date & initial all entries